PASCOE 6.2 - DOUBLE QUICK-TIME UPGRADE AND REFURBISHMENT

GRP Boat Repairs undertook repair and refurbishment projects for the captain of a superyacht, one of which was to completely refit a six-year-old Pascoe 6.2 Beach Lander.

The comprehensive repair and refit program included a full engine overhaul, new upholstery and thorough testing of the electrics with replacements where needed.

One of the first jobs included rectifying minor damage to the bilges. Tenders take a lot of hardware and minor damage to the gelcoat in the bilge is normally widespread. (After picture below)



Tubes where frayed and in a poor condition before. So we used heat guns to softly remove the fraying and pumped the tubes up the correct pressure.


<u>Before</u> <u>After</u>






Any scrapes and dents on the boat were repaired to 'as new' condition, matching the black gelcoat then ceramic coated to protect from UV damage and other elements.

The GRP team also repaired, sanded and sealed the teak decking making it look like new. The teak decking was in a scruffy and poor condition from sun damage, (see picture on the left where dry) so was scrubbed and coated to refresh.





The whole interior of the Beach Lander was replaced and upgraded to match the upholstery material of the other superyachts tender <u>Brig</u> and to match the mothership colours. This entailed copying the stitching style and design on both tenders.

<u>Before</u> <u>After</u>











A major and difficult part of the refurb' program was sourcing, upgrading and replacing the underwater lights. This required rewiring the lighting circuits and perhaps a more difficult task: sourcing suitable units which could stand up to the boat's rigorous day to day use.



Short timelines like this one focus the attention wonderfully. But when one considers the cost of buying a new tender against the cost of a complete refurb, there's no contest, the refurbishment wins every time.

To top it all, the boat was treated to a ceramic coating on the tubes and black gelcoat. Not only does she look good, but she is easy to clean too.

(After ---- Before)









